

Date: Thursday, 6/21/2007 2:29:31 PM
 User: Kim Johnston

Process Sheet

Customer : CU-DAR001 Dart Helicopters Services	Drawing Name : FUEL PURGE CANISTER
Job Number : 33065A	
Estimate Number : 10441	
P.O. Number : <i>N/A</i>	Part Number : D32621
This Issue : 6/21/2007 S.O. No. : <i>N/A</i>	Drawing Number : D3262 REV C
Prsht Rev. : NC	Project Number : N/A
First Issue : <i>N/A</i> Type : MACHINED PARTS	Drawing Revision : C
Previous Run : 32261A	Material : <i>N/A</i>
Written By : <i>[Signature]</i>	Due Date : 7/15/2007 Qty: 6 Um: Each
Checked & Approved By : <i>[Signature] 07.06.22</i>	
Comment : Est. C 05.03.10 Removed P/O for liquid penetrant inspection K J/JLM	

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	M6061T6T5000W125	6061-T6 Tube 5.00X.125W
-----	------------------	-------------------------



Comment: Qty.: 0.9406 f(s)/Unit Total : 5.6435 f(s)

Material: 6061-T6 (QQ-A-200/8 or 225/8) 5.00 OD x 0.125" wall
 (M6061T6T5.000W.125)

Identify as D3262-1

Batch: *102019*

[Signature] Unable to enter inventory

[Signature] 07.09.02

2.0	BAND SAW	BAND SAW
-----	----------	----------



Comment: BAND SAW

Cut D3262-1 to length as per Dwg D3262

Identify as D3262-1

[Signature] 07.09.02

6

3.0	SMALL FAB 1	SMALL & MEDIUM FAB RESOURCE 1
-----	-------------	-------------------------------



Comment: SMALL & MEDIUM FAB RESOURCE 1

Deburr

[Signature] 07.09.02

6

4.0	QC2	INSPECT PARTS AS THEY COME OFF MACHINE
-----	-----	--



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

[Signature] 07.09.02

6

5.0	QC8	SECOND CHECK
-----	-----	--------------



Comment: SECOND CHECK

[Signature] 07/09/03

6

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes ☒ No ☐ DQA: ED Date: 2/09/05
 QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Thursday, 6/21/2007 2:29:31 PM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FUEL PURGE CANISTER

Job Number: 33065A

Part Number: D32621

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: 57164

PO 7/9/07 (6)

7.0

QC21

FINAL INSPECTION/W/O RELEASE



(6)

Comment: FINAL INSPECTION/W/O RELEASE

PO 8/10/05

Job Completion



U 8/10/05

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			


NOTE: Date & initial all entries



DESIGN <i>[Signature]</i>	DRAWN BY <i>[Signature]</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>PH</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D3262	REV. C SHEET 1 OF 2
DATE 06.08.31		TITLE FUEL PURGE CANISTER SCALE 1:4	
REV	DATE	DESCRIPTION	
A	04.05.06	FIRST ISSUE	
B	05.02.14	ADD PRESSURE TESTING OPTION	
C	06.08.31	Ø 5.165 WAS Ø 5.190	

RELEASED

06.09.19 *[Signature]*




D3262-041 CANISTER ASSEMBLY

ITEM	QTY -041	P/N	DESCRIPTION
	X	D3362-041	CANISTER ASSEMBLY
1	1	D3262-1	TUBE
2	2	D3262-3	CAP

NOTES:

- 1) WELD PER DART QSI 004
- 2) BREAK ALL SHARP CORNERS 0.005 TO 0.010
- 3) LIQUID PENETRANT INSPECT PER ASTM E1417 LEVEL 1 OR PRESSURIZE TO 10 psi AND SUBMERGE UNDER WATER TO CHECK FOR LEAKS **B**
- 4) FINISH: CHEMICAL CONVERSION COAT PER QSI 005 4.1 POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3
- 5) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 6) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED
- 7) IDENTIFY WITH DART P/N AND B/N USING FINE POINT PERMANENT INK MARKER





SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. **33065A**

COPYRIGHT © 2004 BY DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.



DESIGN <i>PH</i>	DRAWN BY <i>PH</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>PH</i>	APPROVED <i>PH</i>	DRAWING NO. D3262	REV. C SHEET 2 OF 2
DATE 06.08.31		TITLE FUEL PURGE CANISTER	SCALE 1:4




RELEASED


06.09.19

D3262-1 TUBE

- 1) MATERIAL: 6061-T6 OR 6061-T62 TUBING, 5.00 OD x 0.125 WALL
PER WW-T-700/6 OR AMS 4080 OR AMS 4082 OR
QQ-A-200/8 OR QQ-A-225/8
(REF. DART SPEC. M6061T6T5.000W.125)



SECTION A-A
SCALE 1:2




D3262-3 CAP

- 1) MATERIAL: 6061-T6/T651 (QQ-A-200/8 OR QQ-A-225/8) BAR
(REF. DART SPEC. M6061T6B)

NOTES:

- 2) FINISH: NONE
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED
- 5) BREAK ALL SHARP CORNERS 0.005 TO 0.010
- 6) PART IS SYMMETRICAL ABOUT CENTERLINE
- 7) ENGRAVE 'DART' LOGO AS SHOWN USING 0.75 HIGH x 0.010 DEEP (MAX) LETTERS WITH TOOL RADIUS OF 0.25 (MIN)



DETAIL B
SCALE 2:1

COPYRIGHT © 2004 BY DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.